

Dlook



Report of Residential Building Record (3R)

(Housing Code Section 351(a))

BEWARE: This report describes the current legal use of this property as compiled from records of City Departments. There has been no physical examination of the property itself. This record contains no history of any plumbing or electrical permits. The report makes no representation that the property is in compliance with the law. Any occupancy or use of the property other than that listed as authorized in this report may be illegal and subject to removal or abatement, and should be reviewed with the Planning Department and the Department of Building Inspection. Errors or omissions in this report shall not bind or stop the City from enforcing any and all building and zoning codes against the seller, buyer and any subsequent owner. The preparation or delivery of this report shall not impose any liability on the City for any errors or omissions contained in said report, nor shall the City bear any liability not otherwise imposed by law.

П	Multi-SS of Building	Lot	
O	Other Addresses		
1.	. A. Present authorized Occupancy or use: THREE FAMILY DWELLING		
	B. Is this building classified as a residential condominium? Yes No ✓		
	C. Does this building contain any Residential Hotel Guest Rooms as defined in Chap. 41, S.F. Admin. Code?	Yes Yes	No ✓
2.	. Zoning district in which located: RM-1 3. Building Code Occupancy Classification	ı: R-2	
1.	Do Records of the Planning Department reveal an expiration date for any non-conforming use of this propert If Yes, what date? The zoning for this property may have changed. Call Planning Department, (415) 5	•	No ✓ current status

- 5. Building Construction Date (Completed Date): UNKNOWN
- 6. Original Occupancy or Use: UNKNOWN

Address of Ruilding

7. Construction, conversion or alteration permits issued, if any:

Application #	Permit #	Issue Date	Type of Work Done	Status
		1972	INSTALL 6 ALUMINUM WINDOWS IN EXISTING FRAME	C
	-	1988	HORIZONTAL ADDITION - CONSTRUCT REAR STAIRS, ADD SMALL DECK AT 3RD FLOOR. REPLACE ALL WINDOWS & DOORS AT EXISTING UNHEATED PORCHES. RELOCATE WATER HEATERS. MAKE EXISTING GARDEN STORAGE SHED ROOF FLAT WITH RAILING. CONSTRUCT THREE STORAGE ROOMS	С
		1991	RE-ROOFING	C
		2005	CHANGE CABINETS IN KITCHEN. PAINT, ADD TILES AND REPLACE COUNTER	C
		2011	INSTALLATION OF NEW COPPER WATER SERVICE REPLACEMENT FOR EXISTING GALV SUPPLY, REMOVE OF EXIST CONCRETE FLAGS AND INSTALL OF NEW FLAGS, REMOVE AND REPLACE LIGHT FOR ACCESS (SENSOR LIGHT), REMOVE & REINSTALL WOOD SIDING FOR ACCESS, TIE IN TO EXISTING WATER METER	С
		2015	TO OBTAIN FINAL INSPECTION FOR WORK APAPROVED UNDER ALL WORK IS COMPLETE	C
		2015	TO COMPLY WITH PHYSICAL INSPECTION REPORT	C
		2015	REPLACE 6 FRONT WINDOWS WITH 6 WOOD WINDOWS IN KIND. TO COMPLY WITH PHYSICAL INSPECTION REPORT	С

Department of Building Inspection 1660 Mission Street - San Francisco CA 94103 - (415) 558-6080 Report of Residential Record (3R)

Page 2

Address of Building				Block	Lot	
Other Addresses						
B. A. Is there an active Fi B. Is this property curr D. Number of residential	ently under abatement	proceedings fo	or code violations?		Yes Yes ✔	No s No
0. A. Has an energy insp			B. If yes, has a pr	oof of compliance been is:	sued? Yes ✓	No
•	he Mandatory Earthqua iired upgrade work bee		Wood-Frame Building F Yes No	rogram? Yes No	√	
Date of Issuance:	28 JAN 2016					
Date of Expiration:	28 JAN 2017					
By:			Patty Herrera, I	Nanager		
Report No:			Records Manag	O		
THIS REPORT IS VALI	D FOR ONE YEAR ONLY	• •	y, the seller must deliver this r	mation of the sale or exchange		

(For Explanation of terminology, see attached)

Records Management Division 1660 Mission Street - San Francisco CA 94103 Office (415) 558-6080 - FAX (415) 558-6402 - www.sfdbi.org